


RECOMMENDED CUTTING CONDITIONS

Shoulder milling

Work material	Aluminium alloy A7075		Aluminium cast AC4B		
	Dia. (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Revolution (min ⁻¹)	Feed rate (mm/min)
10	19000	8600	9500	3400	
12	16000	8200	8000	3200	
16	12000	7600	6000	3100	
18	10500	7200	5300	2900	
20	9500	7100	4800	2900	
22	8500	6900	4300	2800	
25	7500	6800	3800	2700	
Depth of cut	≤0.5D ≤1D D: Dia.				


Slotting

Work material	Aluminium alloy A7075		Aluminium cast AC4B		
	Dia. (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Revolution (min ⁻¹)	Feed rate (mm/min)
10	19000	6800	9500	2700	
12	16000	6500	8000	2600	
16	12000	6100	6000	2400	
18	10500	5800	5300	2400	
20	9500	5700	4800	2300	
22	8500	5500	4300	2200	
25	7500	5400	3800	2200	
Depth of cut	 D: Dia				


- 1) If the rigidity of the machine or the workpiece installation is very low, or chattering and noise are generated, please reduce the revolution and the feed rate proportionately, or set a smaller depth of cut.
- 2) If the depth of cut is shallow, the revolution and feed rate can be increased.
- 3) Water-soluble cutting fluid is recommended.
- 4) Climb cutting is recommended for side milling.

Using a high-speed and high-rigidity machining centre

Shoulder milling

Work material	Aluminium alloy A7075		Aluminium cast AC4B	
Dia. (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Revolution (min ⁻¹)	Feed rate (mm/min)
10	30000	11000	19000	5400
12	30000	12000	16000	5300
16	24000	12000	12000	4900
18	21000	12000	10500	4700
20	19000	11000	9500	4600
22	17000	11000	8500	4300
25	15000	11000	7500	4300
Depth of cut				

Slotting

Work material	Aluminium alloy A7075		Aluminium cast AC4B		
	Dia. (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Revolution (min ⁻¹)	Feed rate (mm/min)
10	30000	8600	19000	4300	
12	30000	9900	16000	4300	
16	24000	9700	12000	4000	
18	21000	9500	10500	3800	
20	19000	9100	9500	3700	
22	17000	8700	8500	3400	
25	15000	8600	7500	3400	
Depth of cut	 D: Dia				

- 1) If the rigidity of the machine or the workpiece installation is very low, or chattering and noise are generated, please reduce the revolution and the feed rate proportionately, or set a smaller depth of cut.
- 2) If the depth of cut is shallow, the revolution and feed rate can be increased.
- 3) Water-soluble cutting fluid is recommended.
- 4) Climb cutting is recommended for side milling.