



DRILLING (SOLID CARBIDE)


CARBIDE

MPS,MSL**HOW TO USE LONG TYPE DRILLS****● Drilling a blind hole****■ 1. Drilling a pilot hole**


- ① Use a drill with a larger (flatter) point angle than the super long type. Mitsubishi type MPS is recommended.
- ② Ensure a high precision hole is drilled for the guide.
- ③ Drill depth : Approx 1D or deeper.
(Adjust the pilot hole depth according to the length of the super long type.)

■ 2. Initial cutting with the long type drill


- ① Penetrate the pilot hole at low revolution. (Cutting speed 20—30m/min, feed rate 0.2—0.3mm/rev)
- ② Stop the long type drill 1—3mm short of the pilot hole bottom.

■ 3. Drill the deep hole

- ① Start cutting at the recommended speed and feed with a non-peck (continuous feed) cycle.

■ 4. Drill retraction

- ① After drilling, lower the cutting revolution about 1—2mm short of the hole end. (Cutting speed of around 20—30m/min)
- ② Retract the drill to the pilot hole depth starting point at a feed rate of 3000mm/min.
- ③ Finally, clear the hole at a cutting speed of 20—30m/min and feed rate of 0.2—0.3mm/rev.

● Drilling and breaking through on irregular faces or angles**■ 1. Spot facing**


- ① Machine a flat on the irregular face by using an end mill or slot drill capable of spot facing. Make the spot face diameter the same size as the required deep hole diameter.

■ 2. Drilling a pilot hole

- ① Use a drill with a larger (flatter) point angle than the super long type. Mitsubishi type MPS is recommended.
- ② Ensure a high precision hole is drilled for the guide.
- ③ Drill depth : Approx 1D or deeper.
(Adjust the pilot hole depth according to the length of the super long type.)

■ 3. Initial cutting with the long type drill


- ① Penetrate the pilot hole at a low revolution. (Cutting speed 20—30m/min, feed rate 0.2—0.3mm/rev)
- ② Stop the long type drill 1—3mm short of the pilot hole bottom.

■ 4. Drill the deep hole

- ① Start cutting at the recommended speed and feed with a non-peck (continuous feed) cycle.

■ 5. Breaking through

- ① When breaking through, the cutting edge can be damaged.
- ② A feed rate of 0.05—0.1mm/rev is recommended.

■ 6. Drill retraction

- ① Retract the drill to the pilot hole depth starting point at a feed rate of 3000mm/min.
- ② Finally clear the hole at a cutting speed of 20—30m/min and feed rate of 0.2—0.3mm/rev.