

ROTATING TOOLS

RECOMMENDED CUTTING CONDITIONS (SHANK TYPE)

CUTTING CONDITIONS FOR SHOULDER MILLING

Work Material		Hardness	Insert Grade/Breaker	Cutting Speed vc (m/min)	Width of Cut: ae (mm) Feed per Tooth: fz (mm/tooth)							
					φ 50 (the last letter of order number for cutter body) S (ap≤110) M (ap=157) L (ap=205)				φ 63 (the last letter of order number for cutter body) S (ap=110) M (ap=157) L (ap=205) X (ap=261)			
P	Mild Steel	≤180HB	VP15TF	WH	120 (100—140)	≤10.0 0.15—0.25	≤5.0 0.15—0.25	≤2.5 0.10—0.20	≤12.5 0.15—0.25	≤10.0 0.15—0.25	≤5.0 0.15—0.25	≤2.5 0.10—0.20
				JM	120 (100—140)	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15	≤10.0 0.10—0.20	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15
	Carbon Steel Alloy Steel	180—350HB		WH	80 (70—120)	≤10.0 0.15—0.25	≤5.0 0.15—0.25	≤2.5 0.10—0.20	≤12.5 0.15—0.25	≤10.0 0.15—0.25	≤5.0 0.15—0.25	≤2.5 0.10—0.20
				JM	80 (70—120)	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15	≤10.0 0.10—0.20	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15
	Alloy Tool Steel	≤300HB		WH	80 (60—100)	≤10.0 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15	≤12.5 0.10—0.20	≤10.0 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15
				JM	80 (60—100)	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.05—0.10	≤10.0 0.10—0.15	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.05—0.10
M	Stainless Steel	≤200HB	VP20RT	WH	80 (60—100)	≤7.5 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10	≤10.0 0.08—0.15	≤7.5 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10
				JM	80 (60—100)	≤5.0 0.08—0.15	≤3.5 0.08—0.15	≤2.0 0.05—0.10	≤7.5 0.08—0.15	≤5.0 0.08—0.15	≤3.5 0.08—0.15	≤2.0 0.05—0.10
K	Cast Iron	Tensile Strength ≤350MPa	VP15TF	WH	100 (80—120)	≤10.0 0.15—0.40	≤5.0 0.15—0.35	≤2.5 0.10—0.30	≤12.5 0.15—0.40	≤10.0 0.15—0.40	≤5.0 0.15—0.35	≤2.5 0.10—0.30
				JM	100 (80—120)	≤7.5 0.10—0.25	≤5.0 0.10—0.25	≤2.5 0.05—0.20	≤10.0 0.10—0.25	≤7.5 0.10—0.25	≤5.0 0.10—0.25	≤2.5 0.05—0.20
	Ductile Cast Iron	Tensile Strength ≤800MPa		WH	80 (60—100)	≤10.0 0.15—0.35	≤5.0 0.15—0.30	≤2.5 0.10—0.25	≤12.5 0.15—0.35	≤10.0 0.15—0.35	≤5.0 0.15—0.30	≤2.5 0.10—0.25
				JM	80 (60—100)	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15	≤10.0 0.10—0.20	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.05—0.15
S	Ti Alloy	≤350HB	VP20RT	WH	40 (35—50)	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10	≤7.5 0.05—0.10	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10
				JM	40 (35—50)	≤3.5 0.05—0.10	≤2.5 0.05—0.10	≤1.5 0.05—0.10	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.5 0.05—0.10	≤1.5 0.05—0.10

(Note 1) The above cutting conditions are determined based on high rigidity machine and workpiece, where no vibration occurred.

Please adjust the machining conditions if vibration is generated.

(Note 2) For the tools of cutting edge length is 200mm or more, please reduce the cutting speed and table feed by 10-20% and the cutting width by 50%.

(Note 3) If the cutting angle between the tool and workpiece exceeds 90° when machining corners. Reduce the cutting speed and table feed by 10-20% and a_e by 50%. Also if possible, set a radius cutting path for corners.

CUTTING CONDITIONS FOR SLOT MILLING

Work Material	Hardness	Insert Grade/Breaker	Cutting Speed vc (m/min)	Width of Cut: ap (mm) Feed per Tooth: fz (mm/tooth)							
				φ 50 (the last letter of order number for cutter body) S (ap=110) M (ap=157) L (ap=205)			φ 63 (the last letter of order number for cutter body) S (ap=110) M (ap=157) L (ap=205) X (ap=261)				
P	Mild Steel	VP15TF	WH	60 (50—120)	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15	≤12.5 0.10—0.25	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15
			JM	60 (50—120)	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15	≤10.0 0.10—0.15	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15
	Carbon Steel Alloy Steel		WH	60 (50—100)	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15	≤12.5 0.10—0.25	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15
			JM	60 (50—100)	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15	≤10.0 0.10—0.15	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15
	Alloy Tool Steel		WH	50 (40—80)	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15	≤12.5 0.10—0.25	≤10.0 0.10—0.25	≤5.0 0.10—0.20	≤2.5 0.10—0.15
			JM	50 (40—80)	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15	≤10.0 0.10—0.15	≤7.5 0.10—0.15	≤5.0 0.10—0.15	≤2.5 0.10—0.15
M	Stainless Steel	VP20RT	WH	40 (35—80)	≤10.0 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10	≤12.5 0.08—0.15	≤10.0 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10
			JM	40 (35—80)	≤7.5 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10	≤10.0 0.08—0.15	≤7.5 0.08—0.15	≤5.0 0.08—0.15	≤2.5 0.05—0.10
K	Cast Iron	VP15TF	WH	50 (40—80)	≤10.0 0.15—0.25	≤5.0 0.10—0.25	≤2.5 0.10—0.20	≤12.5 0.15—0.25	≤10.0 0.15—0.25	≤5.0 0.10—0.25	≤2.5 0.10—0.20
			JM	50 (40—80)	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.10—0.20	≤10.0 0.10—0.20	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.10—0.20
	Ductile Cast Iron		WH	40 (35—80)	≤10.0 0.15—0.25	≤5.0 0.10—0.25	≤2.5 0.10—0.20	≤12.5 0.15—0.25	≤10.0 0.15—0.25	≤5.0 0.10—0.25	≤2.5 0.10—0.20
			JM	40 (35—80)	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.10—0.20	≤10.0 0.10—0.20	≤7.5 0.10—0.20	≤5.0 0.10—0.20	≤2.5 0.10—0.20
S	Ti Alloy	VP20RT	WH	35 (30—50)	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10	≤7.5 0.05—0.10	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10
			JM	35 (30—50)	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10	≤7.5 0.05—0.10	≤5.0 0.05—0.10	≤3.5 0.05—0.10	≤2.0 0.05—0.10

(Note 1) The above cutting conditions are determined based on high rigidity machine and workpiece, where no vibration occurred.

Please adjust the machining conditions if vibration is generated.

(Note 2) For slotting, please use high rigidity tools such as SPX4R05016WNES/BT50NES.