




CHIP CONTROL RANGE FOR WORK MATERIALS

Finish Cutting..... Light Cutting..... Medium Cutting.....



Cutting Conditions (Guide) : ● : Stable Cutting ● : General Cutting ✖ : Unstable Cutting

Work Material	P	Steel	    	    	                    	
---------------	---	-------	---	---	--	---

● : Inventory maintained. ★ : Inventory maintained in Japan.