




CHIP CONTROL RANGE FOR WORK MATERIALS

Finish Cutting..... Medium Cutting.....



Cutting Conditions (Guide) : ● : Stable Cutting ● : General Cutting ✖ : Unstable Cutting

[illegible]

TURNING INSERTS

POSI
11°

WITH
HOLE

C

D

B

S

T

V

W

K

CHIP BREAKERS	➤ A062
GRADES	➤ A030
IDENTIFICATION	➤ A002